

Case No.	Respondent	Summary of Findings	Summary of Board Action
MARCH 27, 2007			
HI07-065	Roberto Chavez Home Inspection #38553	On or about October 30, 2006, <i>Respondent was convicted of A Class 6 Undesignated Felony.</i> As of May 14, 2008 charge has been reduced to a misdemeanor and all probation requirements have been successfully met. Respondent has petitioned and received an early termination of probation by the Superior Court of the State of Arizona in Maricopa County. Therefore the Board of Technical Registration Terminates its concurrent probation order as of June 2, 2008.	Probation – Respondent Home Inspector registration No. 38553 shall be placed on three years probation concurrent with court ordered probation dated November 30, 2006. Respondent shall comply with terms and conditions set by the Maricopa County Adult Probation Department. Respondent shall provide to the Board monthly probation fee receipts along with copies of random drug and alcohol test results. Cost of Investigation – Pay cost of Investigation in the amount of \$81.00.
MAY 22, 2007			
HI07-075	Brent S.Ruttle Home Inspection #41248	On or about October 1, 2004, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: garage door and auto-reverse safety feature; condition of wall structure; operation of entry doors; piping supports and insulation; functional flow; type and condition of waste and vent piping; condition of electrical service ground; type of branch circuit conductors; GFCI protection in the garage; type and condition of fireplace; condition of HVAC filters and heating/cooling source in each room; garage fire separation walls, ceiling and door; laundry dryer ventilation; condition of fuel supply piping; and conducted home inspection without firm registration.	Letter of Reprimand Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score. Cost of Investigation – Pay cost of Investigation in the amount of \$200.00.
JUNE 26, 2007			
HI07-080 HI07-088	Alex H. Herrera Home Inspection #39797	On or about November 20, 2004, and September 21, 2005, Respondent performed home inspections and prepared a reports that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: method used to observe the roof; condition of the under floor crawl space; plumbing functional flow and drainage; condition of plumbing piping and supports; the presence of a heating and cooling source in each room condition of the dryer vent; type of attic insulation; properly report a recommendation for further action on the garbage disposal.	Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score. Cost of Investigation – Pay cost of Investigation in the amount of \$200.00.
M06-048	Scott D. Lowry Home Inspection #40493	On or about May 4, 2005, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>failed to make recommendations to correct, monitor, or evaluate by appropriate</i>	Assurance of Discontinuance Civil Penalty – Pay Civil Penalty in the amount of \$2,000.00. Cost of Investigation – Respondent shall pay cost of

		<i>persons for the HVAC unit condition; report proper type of garage door; conducted a home inspection with expired registration.</i>	Investigation in the amount of \$270.00.
HI07-084	Scott D. Lowry Nonregistrant	On or about May 9, 2007, <i>during an enforcement advisory committee on case # M06-048, Respondent admitted to performing home inspections while having expired registration since February 28, 2005. Respondent admitted to operating Five Star Inspections performing home inspections in the State of Arizona as an unlicensed firm.</i>	Assurance of Discontinuance Civil Penalty – Pay a civil penalty in the amount of \$4,000.00. Costs of Investigation – Pay cost of investigation in the amount of \$70.00.
M06-088	Thomas J. Mattingly Home Inspection #39074	On or about June 7, 2005, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: service current rating and distribution panel ground condition; type and condition of the service entrance conductors over current protection devices; <i>conducted home inspection without current firm registration.</i>	Letter of Reprimand Costs of Investigation – Pay costs of investigation in the amount of \$200.00.
M06-329	Kirt D. Klingerman Home Inspection #38968	On or about September 3, 2003, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>properly report open seams; lifted nails; on the patio roof and the drainage system; flashings and trim for the entire roof; condition of the main electrical panel and disconnect; and type of service conductor; plumbing functional drainage.</i>	Letter of Reprimand Open book test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score. Administrative Penalty – Pay administrative penalty in the amount of \$200.00. Cost of Investigation – Pay cost of investigation in the amount of \$340.00.
AUGUST 28, 2007			
M06-095	Jeff Schroeder Home Inspector #40183	On or about June 26, 2004, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: failed to report incorrectly spliced wires in the attic; Respondent’s report noted the following items were in need of repair, however failed to make recommendations to correct, monitor, or have evaluated by the appropriate persons for the remedy of the following adverse conditions: portions of wood siding dry and slightly buckled, sections of wood trim on the ceiling dry and separating, exterior faucets were not equipped with anti siphon devices, interior cover panel for main electric panel is not labeled properly, bedroom door had a small hole on it’s backside, master and hall bathroom faucets were not functional, microwave fan and light were not functional,	Letter of Reprimand Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score. Costs of Investigation – Pay costs of investigation in the amount of \$100.00.

		missing outlet cover next to the stove, suspected S-trap at laundry sink, firewall separation between house and garage, no fire rated garage entry door and attic door missing, no auto reverse operation on garage door, main water shut off valve broken.	
HI07-046	Edward R. Nusso Home Inspector #38983	On or about August 23, 2006, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: type of interior plumbing supply and waste piping, supports and insulation, functional flow and drainage; fuel distribution piping and supports, heating safety controls; condition of main electrical panel, and branch circuit conductors; and Failed to report installed heat source presence in each room, and condition of heating and cooling filters.	<p>Letter of Reprimand</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$100.00.</p>
HI07-049	Gary D. Meltzer Home Inspector #42488	On or about August 14, 2006, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>condition of the roof</i> ; Failed to obtain a signed inspection agreement; type and condition of structural components, foundation, floors, walls, columns, ceilings; exterior flashing and trim, eaves, soffits and fascias; plumbing supports, insulation, waste and vent piping, functional flow and drainage; electrical service ground and branch circuit conductors; type of HVAC, heating and cooling sources, energy source, automatic safety controls, and filter condition; interior condition of fire separation walls, ceilings, and doors; attic insulation, attic, bathroom, and dryer vents.	<p>Letter of Reprimand</p> <ul style="list-style-type: none"> Probation – Respondent’s Home Inspector Registration No. 42488 shall be placed on probation until the following requirement is met: <p>Restitution – Pay restitution to Mr. & Mrs. Pehrson in the amount of \$300.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$100.00.</p>
HI07-086	Mark L. Formanek Home Inspector #40392	On or about April 27, 2007, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: wall structures; columns; representative number of windows and switches; report functional flow and drainage; water heater automatic safety controls; report a heating and cooling source in each room; During Respondent’s inspection of the safety reverse feature of the garage door, <i>Respondent placed his arm in the path as the door was closing and damaged the garage door.</i> He indicated there was damage to the garage door as excessive at the time of the inspection in his report.	<p>Letter of Reprimand</p> <ul style="list-style-type: none"> Probation Respondent’s Home Inspection Certification No. 40392 shall be placed on probation until the following requirement is met: <p>Restitution - Pay restitution to Mr. & Mrs. Carson in the amount of \$1000.00.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$100.00.</p>
SEPTEMBER 25, 2007			

M05-196	Arthur McKay Home Inspector #38657	On or about March 23, 2004, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>condition of interior distribution piping, functional flow and drainage</i> , and plumbing supports; <i>failed to recommend corrective action for low water volume in supply system plumbing</i> ; statement that the inspection is performed in accordance with the Arizona Standards of Professional Practice for Home Inspectors; operation and condition of all GFCI devices; visible fuel piping, and material used for drip leg; and note registration number in home inspection report.	<p>Letter of Reprimand</p> <ul style="list-style-type: none"> Probation Respondent's Home Inspection Certification No. 38657 shall be placed on probation until the following requirement is met: <p>Restitution – Pay restitution to Mr. Mercer in the amount of \$200.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board's Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$390.00.</p>
HI07-039	Thomas E. Sullivan Home Inspector #38636	On or about June 20, 2006, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: plumbing functional flow and functional drainage; report presence of a heating and cooling source in each room; attic and laundry ventilation.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay administrative penalty in the amount of \$100.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board's Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$160.00.</p>
HI07-097	Bruce S. Hubbard Home Inspector #38582	On or about January 27, 2007, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: method used to access attic; plumbing fixtures and faucets, cross connections, type of supply and distribution piping, functional drainage; exterior GFCI protection, thermostat, heating automatic safety controls; air filter condition, installed heat and cooling source presence in each room; fire separation walls, ceilings, and doors.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay administrative penalty in the amount of \$100.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board's Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$85.00.</p>
OCTOBER 23, 2007			
M05-230	Jerry J. Brown Home Inspector #38961	On or about August 18, 2004, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>report properly on the condition of the HVAC system; GFCI protection at pool light; fuel</i>	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$2000.00.</p> <p>Open Book Test – Take and successfully complete an open</p>

		<p>pipng and supports; heating safety controls; cooling unit air filter; and on all exterior hose faucets.</p>	<p>book test on the Board's Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$270.00.</p>
M06-331	Randall A. Marlatt Home Inspector #38148	<p>On or about February 4, 2004, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>report an unsafe low hanging electrical line between two structures</i>; method used for inspecting crawl space; heating system safety controls; and a heating source in each room.</p>	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$500.00.</p> <ul style="list-style-type: none"> • Probation Respondent's Home Inspection Certification No. 38148 shall be placed on probation until the following requirement is met: <p>Restitution – Pay restitution to Ms. Stees in the amount of \$275.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board's Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$410.00.</p>
M05-035	Roger D. Ross Home Inspector #38607	<p>On or about December 23, 2003, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>type and condition of the service conductor, service amperage and voltage ratings; the lack of a 240 volt breaker for a 240 volt appliance, and improper visible wiring at the water heater</i>; operation of the garage automatic opener and safety reverse feature; functional flow and functional drainage; observation method of the attic; heating and cooling source in each room; air filters; condition of the main breakers and panel; compatibility of the branch circuits/breakers; and adequately report on the dryer vent.</p>	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$500.00.</p> <ul style="list-style-type: none"> • Probation Respondent's Home Inspection Certification No. 38607 shall be placed on probation until the following requirement is met: <p>Restitution – Pay restitution to Ms. Barnett in the amount of \$265.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board's Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$470.00.</p>
M05-044	Floyd E. Otwell Home Inspector #38215	<p>On or about May 17, 2004, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to</p>	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the</p>

		adequately address the following areas: roof and ceiling structural components; observation of attic area or if attic was present; report functional drainage; flues and vents; type of electrical service conductor; location of the main electrical panel; safety controls for heating equipment; attic ventilation and insulation, and kitchen ventilation.	amount of \$100.00. Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score. Costs of Investigation – Pay costs of investigation in the amount of \$156.00.
HI07-094	Randy R. West Home Inspector #38451	On October 20, 2006, <i>Respondent’s financial assurance bond was cancelled. The Board was notified in writing on October 23, 2006 by RLI Surety by Notice of Cancellation. Thereafter Respondent conducted various home inspections and issued inspection reports without financial assurance until May 2, 2007. Respondent’s firm registration expired on February 28, 2007; Professional Building Consultants, Inc. offered home inspection services to the public without current registration until May 2, 2007. Respondent’s individual registration also became delinquent on April 30, 2007 and remained delinquent until May 2, 2007.</i>	Letter of Reprimand Administrative Penalty – Pay an administrative penalty in the amount of \$1000.00. Costs of Investigation – Pay cost of investigation in the amount of \$65.00.
M06-077	Mathew L. Moskowitz Home Inspector #41145	On or about April 4, 2005, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: statement that the inspection is performed in accordance with the Arizona Standards of Professional Practice for Home Inspectors; report type and condition of columns; <i>condition of flashings and trim</i> ; report adverse impact of vegetation on structure; <i>condition of patio lattice; rear patio grading; patio structural connections; roof drainage system</i> ; roof covering type and structure; <i>damaged wood posts and roof</i> ; <i>report on dishwasher drain hose</i> ; distribution piping supports; functional drainage; heating and cooling safety controls; type and <i>condition of HVAC system; and condition and operation of exterior doors.</i>	Voluntary Surrender – Deemed to be a Revocation, Respondent agrees to voluntarily surrender his home inspector registration no. 41145. Administrative Penalty – Pay an administrative penalty in the amount of \$500.00. Restitution - Pay restitution to Mr. Lutick in the amount of \$174.00. Costs of Investigation – Pay costs of investigation in the amount of \$500.00.
M06-046	David Sandoval Home Inspector #38462	On or about March 19, 2005, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: include firm address and inspectors Arizona registration number in agreement; statement that the inspection is performed in accordance with the Arizona Standards of Professional Practice; report condition and operation of all exterior doors; operation of a representative number of windows; observe and report on roof drainage systems; plumbing functional drainage; water heater flues and vents; main electrical service conductors; electrical circuit compatibility; representative number of	Letter of Reprimand Administrative Penalty – Pay administrative penalty in the amount of \$100.00. Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score. Costs of Investigation – Pay costs of investigation in the amount of \$182.00.

		light switches; heating system thermostat; presence of a heating source in each room; and kitchen ventilation.	
M06-275	Daniel Haydon Home Inspector #38067	On or about September 13, 2004, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: statement the inspection was done in accordance with the Standards of Professional Practice for Arizona Home Inspectors; report plumbing functional flow and drainage; and report a heating and cooling source in each room.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay administrative penalty in the amount of \$250.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$398.00.</p>

NOVEMBER 27, 2007

M05-033	Geary G. Morris Home Inspector #38596	On or about February 10, 2004, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: include firm address in agreement; observation methods for structural components; report type and condition of exterior wall cladding; observe and report on interior and exterior doors and garage door opener; plumbing pipe supports/insulation and functional flow; water heater automatic safety controls; electrical service ground, overcurrent protection devices, main panel, service voltage rating, branch circuit conductors, compatibility, GFCI devices; HVAC condition, energy source, operating and safety controls, flues and vents, distribution system, air filters, heating and cooling source in each room; and fire separation walls and doors, and laundry ventilation.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay administrative penalty in the amount of \$250.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$208.00.</p>
---------	--	---	---

M06-073	Nolan C. Udall Home Inspector #38747	On or about September 3, 2004, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>condition of the roof; obtain a signed inspection agreement by the client, at the direction of the client respondent signed the contract for client; properly recommend correcting, monitoring, or evaluating by appropriate persons missing rear deck steps and missing railing; and conducted an inspection without using the Standards of Professional Practice for Home Inspectors in the State of Arizona at the request of the client.</i>	<p>Letter of Reprimand</p> <p>Voluntary Surrender – Deemed to be a Revocation, Respondent agrees to voluntarily surrender his Arizona Home Inspectors Registration No. 38747. The Board will consider this to be a disciplinary action for failure to meet the reporting standards of the Standards of Professional Practice for Arizona Home Inspectors. Respondent also agrees he will not submit an application for Home Inspector Registration in the State of Arizona for Five (5) years.</p> <p>Cost of Investigation – Pay costs of investigation in the amount of \$200.00.</p>
---------	---	--	--

DECEMBER 18, 2007

<p>M05-023 M06-240 M06-325 M06-327</p>	<p>John R. Reding Home Inspector #38663</p>	<p>On or about March 11, 2004, Respondent performed home inspections and prepared reports that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>report multiple heating and cooling system defects</i>; advise client on recommended course of action for adverse items noted; describe method of crawl space observation; report on the condition of porches and decks; condition of roof flashings; distribution piping type and condition, supports and insulation; fixtures and faucets; plumbing waste/vent piping and supports; water heating safety controls, flues and vents; type of electrical service conductor, lights, switches and ground; heating and cooling system filters; kitchen counters, cabinetry and ventilation; <i>exterior electrical receptacles</i>; type of roof at addition; describe method of attic observation; improperly described the roof covering type as asphalt; plumbing system functional drainage; solid fuel heating device; fire separation walls; <i>bathroom ventilation</i>; condition and operation of exterior doors; heating and cooling source in each room; condition of the exterior deck; and operate a representative number of windows.</p>	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$500.00.</p> <p>Probation until the following is met:</p> <p style="padding-left: 40px;">Restitution – a. Pay restitution to Mr. Goeser in the amount of \$240.00. b. Pay restitution to Mr. Young in the amount of \$240.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$800.00.</p>
<p>M05-312</p>	<p>Brian K. Dickinson Home Inspector #39666</p>	<p>On or about August 28, 2004, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>observe and report on all structural components including the foundation and floors in the Arizona room</i>; <i>observe and report on adverse conditions impacting the structure due to grading and drainage on the west side of the home</i>; statement that the inspection is performed in accordance with the Arizona Standards of Professional Practice for Home Inspectors; include registration number in agreement; report type and condition of the trusses; describe attic observation method; and report on plumbing functional flow and functional drainage.</p>	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$2000.00.</p> <p>Probation until the following is met:</p> <p style="padding-left: 40px;">Restitution – Pay restitution to Mr. & Mrs. Bentley in the amount of \$305.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$220.00.</p>
<p>HI08-003</p>	<p>Douglas B. Mason Home Inspector #38656</p>	<p><i>Respondent’s firm registration expired on January 31, 2005, Personalized Inspection Services, L.L.C. offered home inspection services to the public without current registration until September 6, 2007. Respondent’s individual registration also became delinquent on April 30, 2006 and remained delinquent until September 6, 2007.</i></p>	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$1000.00.</p> <p>Costs of Investigation – Pay cost of investigation in the amount of \$65.00.</p>
<p>HI07-092</p>	<p>Joseph J. Dorner Home Inspector #38447</p>	<p>On or about May 25, 2007, Respondent performed a home inspection and prepared a report that failed to meet the Standards of</p>	<p>Letter of Reprimand</p>

		Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: method used to access attic; report condition and operation of all exterior doors; garage door opener and safety reverse feature; make recommendations for remedies on adverse conditions noted in report; report on plumbing functional flow and drainage; plumbing exterior faucets; water heater automatic safety controls; electrical service type and material present; and report on location and condition of main and distribution panels.	<p>Administrative Penalty – Pay administrative penalty in the amount of \$200.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$41.00.</p>
M05-228	Kent L. Dean Home Inspector #39959	On or about September 29, 2004, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>report properly on the condition of the main heating system</i> ; observe one of the heating units present, accurately observe and describe the cooling system; report on heating safety controls; HVAC distribution systems; heating and cooling source in each room; exterior trim; type of roof covering; type service entrance electric voltage; plumbing functional flow and drainage; garage door safety reversing mechanism; attic ventilation; insulation; and laundry dryer ventilation.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$250.00.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$430.00.</p>
JANUARY 22, 2008			
HI07-083	Dennis L. Boswell Home Inspector #40789	On or about May 1, 2006, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: type and condition of the floors, walls, and columns present; condition of plumbing supports; report plumbing functional flow and drainage; waste and vent piping systems; condition of fuel distribution system and supports; overcurrent protection, and GFCI devices; heating system automatic safety controls; heating and cooling distribution systems; heating and cooling source in each room; and attic ventilation.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay administrative penalty in the amount of \$100.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$56.00.</p>
HI07-087	Gary H. Oberbeck Home Inspector #38661	On or about December 15, 2003, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>provide a reason for not fully accessing the attic to observe and report on the presence of adverse items; such as cut trusses, ceiling fan wiring, and inadequate insulation levels in attic due to unknown reason for restricted access to attic</i> ; Improperly reported roof trusses as combination type; include the word amps in description of service amperage; failed to correct reporting inconsistencies on water heater	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$1,000.00.</p> <p>Probation until the following is met:</p> <p>Restitution – Pay restitution to Mr. Kaufman in the amount of \$260.00.</p>

		flue pipes, GFCI outlets, and the gas valve at water heater. The items were listed as satisfactory as well as non applicable and as safety concerns.	<p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$146.00.</p>
FEBRUARY 26, 2008			
M06-080	Daniel E. Glines Home Inspector #38850	On or about July 9, 2005, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>report the lack of GFCI outlets in kitchen and outside receptacles</i> ; report firm address; statement that the inspection is performed in accordance with the Arizona Standards of Professional Practice; obtain a signed inspection agreement; properly report operation of a representative number of windows; type and condition of columns; condition of the trusses; plumbing supports and insulation; drain waste and vent piping material; operation of all fixtures; functional flow and drainage; water heater automatic controls; electrical service conductor material; proper electrical service voltage; heating and cooling registers for each room; garage safety reverse feature; lack of self closing interior door to garage; report heater as electric energy source; and properly address bathroom ventilation.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$300.00.</p> <p>Probation until the following is met:</p> <p style="padding-left: 40px;">Restitution – Pay restitution to Mr. Starrett in the amount of \$250.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$220.00.</p>
HI07-061	Patrick A. Oekerman Home Inspector #38598	On or about October 4, 2006, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>condition of the garage electrical panel</i> ; <i>report exposed overhead wiring in garage</i> ; obtain a signed inspection agreement; include home inspector certification number in the agreement; statement that the inspection is performed in accordance with the Standards of Professional Practice for Home Inspectors in the State of Arizona; grading and drainage of the property; type and condition of structural columns; plumbing supports and insulation; report on all exterior faucets; accurately report heating system capacity in report; heating and cooling source in each room; report unlabeled branch circuits in main distribution panel, and electrical service conductor type; roof drainage system present; and report the significance of the cut trusses and gave no recommendation for further evaluation.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$500.00.</p> <p>Probation until the following is met:</p> <p style="padding-left: 40px;">Restitution – Pay restitution to Mr. Pulley in the amount of \$275.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$156.00.</p>
M05-301	Steven P. Schexneider Home Inspector #38664	<i>Respondent’s firm registration expired on August 31, 2007, Accu-Spec Home Inspections, LLC. Then offered home inspection services</i>	<p>Letter of Reprimand</p>

		<p>to the public without current registration until January 29, 2008. Respondent's individual registration also became delinquent on November 30, 2007 and remained delinquent until January 29, 2008.</p> <p>On or about September 27, 2004, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: type and condition of exterior walls; type and condition of structure columns; plumbing and gas supports; plumbing waste and vent piping; method used to inspect the attic; HVAC filters, heating and cooling source in each room; and report on all entry doors.</p>	<p>Administrative Penalty – Pay an administrative penalty in the amount of \$300.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board's Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$280.00.</p>
MAY 13, 2008			
HI08-006	Larry D. McCrea Home Inspector #41324	<p>Respondent is the holder of delinquent Arizona Home Inspector Certification No. 41324. Respondent conducted various home inspections, and issued inspection reports until April 17, 2008. Respondent's firm registration expired on September 30, 2005. LDM Inspection Services offered home inspection services to the public without current registration.</p> <p>Respondent's individual registration expired on August 31, 2006. Respondent's financial assurance expired on August 16, 2005.</p>	<p>Assurance of Discontinuance</p> <p>Civil Penalty – Pay a civil penalty in the amount of \$6,000.00.</p> <p>Costs of Investigation – Pay cost of investigation in the amount of \$100.00.</p>
M05-363	Barry C. Mahoney Home Inspector #40477	<p>On or about October 20, 2004, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>report water heater wiring improper</i>; structural components including columns present, floors, and walls; report on method used to observe attic and roof; condition of the exterior wall cladding, and interior floors; type and condition of interior plumbing supply and distribution piping; plumbing distribution piping supports and insulation; plumbing functional flow and drainage; electrical service amps and voltage ratings; type and condition of heating and cooling distribution systems; and report on an installed heating and cooling source in each room.</p>	<p>Letter of Reprimand</p> <p>Voluntary Surrender – Deemed to be a Revocation, Respondent agrees to voluntarily surrender his home inspector registration #40477.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$230.00.</p>
M06-229	Francis C. Scruggs Home Inspector #38610	<p>On or about March 3, 2005, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>report water stains on utility room ceiling; report flex ducts lying on the floor; report on a separate heating and cooling distribution system</i>; report on under crawl space and its components; type and condition of the foundation and floor structure; furnace automatic safety controls; operation of a representative number of windows and interior doors;</p>	<p>Letter of Reprimand</p> <p>Voluntary Surrender – Deemed to be a Revocation, Respondent agrees to voluntarily surrender his home inspector registration #38610.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$200.00.</p>

		include inspectors name in agreement; statement that the inspection is performed in accordance with the Arizona Standards of Professional Practice for Home Inspectors; make a proper recommendation for missing roof shingles, and inoperative kitchen exhaust fan.	
JUNE 24, 2008			
HI08-018	Richard M. Nelsen Nonregistrant	Respondent is not registered in the State of Arizona to perform home inspections. <i>Respondent conducted a home inspection for a family friend on his possible home purchase in Payson. Karik Construction Co., Inc. offered a home inspection service and issued a home inspection report and invoice without current individual or firm registration.</i>	Assurance of Discontinuance Civil Penalty – Pay a civil penalty in the amount of \$500.00. Costs of Investigation – Pay cost of investigation in the amount of \$90.00.
HI07-091	John W. Phelps Home Inspector #40657	On or about May 24, 2006, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>condition of the patio roof</i> ; statement that the inspection is performed in accordance with the Standards of Professional Practice for home inspectors in the state of Arizona; type and condition of structural columns; roof flashings, trim, eaves, fascias, and drainage systems; representative number of windows; plumbing pipe supports, supply and waste piping material present; plumbing functional flow and drainage; condition of electrical main service; electrical service ground; heating automatic safety controls; a heat source in each room; type of cooling equipment present; fire separation walls present; attic insulation present; and visible vapor retardant present.	Letter of Reprimand Administrative Penalty – Pay an administrative penalty in the amount of \$1000.00. Probation until the following is met: Restitution - Pay restitution to Ms. Dost in the amount of \$245.00. Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score. Costs of Investigation – Pay costs of investigation in the amount of \$151.00.
M06-176	Philip D. Evard Home Inspector #39986	On or about March 2, 2005, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>report a broken bedroom window seal</i> ; report plumbing functional flow and functional drainage; and failed to obtain a signed inspection agreement.	Letter of Reprimand Voluntary Surrender – Deemed to be a Revocation, Respondent agrees to voluntarily surrender his home inspector registration #39986. Costs of Investigation – Pay costs of investigation in the amount of \$174.00.
JULY 22, 2008			
HI07-077	Harris A. Breit Home Inspector #38058	On or about August 18, 2006, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>condition of the fireplace crown and fire box</i> ; type and condition of structural columns;	Letter of Reprimand Administrative Penalty – Pay an administrative penalty in the amount of \$500.00.

		plumbing pipe supports and insulation; plumbing functional flow and drainage; type of plumbing vent piping material present; and report on fuel piping supports.	<p>Probation until the following is met:</p> <p>Restitution - Pay restitution to Ms. Wagner in the amount of \$240.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$105.00.</p>
HI08-020	Kevin A. Shroyer Home Inspector #42275	On or about January 9, 2007, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: type plumbing waste and vent material present; plumbing pipe supports and insulation; type and condition of columns present; and type and condition of visible vapor retardant present.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay administrative penalty in the amount of \$100.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$61.00.</p>
M05-377	Kent L. Dean Home Inspector #39959	On or about November 4, 2004, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: structural components including floor and walls; water heater safety controls; type and condition of electrical overcurrent protection present; report electrical lights, switches, and receptacles; type and condition of HVAC distribution systems; condition of the balcony and railing components; fire separation walls and doors; bathroom ventilation in half bath location; and condition of roof drainage system present.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay administrative penalty in the amount of \$100.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$61.00.</p>
HI09-002	Roderic N. O’Connor Home Inspector #48344	<i>Respondent conducted a home inspection and issued an inspection report without registration on April 15, 2008. Respondent reported on May 14, 2008 having done 30 parallel inspections submitted during the application process. One of the properties inspected was the April 15, 2008 inspection and was done without supervision and for a fee paid directly to the Respondent. Respondent then turned this address in to the Board as part of his 30 parallel log inspections. Respondent has not completed the Sonoran Desert Institute parallel program having only completed 29 parallel inspections and has not paid school in full. July 7, 2008 respondent</i>	<p>Letter of Reprimand</p> <p>Probation – Respondent shall be placed on probation for 1 year.</p> <p>Restitution – Pay Sonoran Desert Institute \$750.00 for parallel schooling provided.</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$4000.00.</p>

		<i>sent in his 30th parallel inspection done with a certified inspector. Additionally respondent offered home inspection services to the public without financial assurance on July 9, 2008. Respondent has not provided the Board proof of financial assurance as of July 22, 2008.</i>	Costs of Investigation – Pay cost of investigation in the amount of \$81.00.
HI08-019	Paul A. Juarez Home Inspector #40316	On or about February 27, 2007, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: type and condition of columns present; plumbing functional flow and functional drainage; report the presence of a heating and cooling source in each room; and condition of kitchen and laundry ventilation.	Letter of Reprimand Administrative Penalty – Pay administrative penalty in the amount of \$100.00. Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score. Costs of Investigation – Pay costs of investigation in the amount of \$55.00.

AUGUST 26, 2008

HI08-007	Paul T. Bernard Home Inspector #38445	On or about November 6, 2007, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>condition of the gas fireplace, and give a reason he was unable to check fireplace components</i> ; statement that the inspection is performed in accordance with the Arizona Standards of Professional Practice for Home Inspectors in Arizona; report method used to observe attic; plumbing functional flow and drainage; type plumbing waste and vent material present; heating and cooling source in each room; condition of the dryer vent; and failed to give recommendations to correct, monitor or evaluate by appropriate persons adverse conditions present.	Letter of Reprimand Administrative Penalty – Pay administrative penalty in the amount of \$500.00. Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score. Costs of Investigation – Pay costs of investigation in the amount of \$104.00.
HI08-008	William C. Baber Home Inspector #38070	On or about March 7, 2007, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>condition of the patio roof; accurately report type of roofing material present at patio roof</i> ; statement that the inspection is performed in accordance with the Arizona Standards of Professional Practice; type and condition of columns present; type and condition of electrical service present.	Letter of Reprimand Administrative Penalty – Pay administrative penalty in the amount of \$500.00. Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score. Costs of Investigation – Pay costs of investigation in the amount of \$108.00.

SEPTEMBER 23, 2008

HI08-009	John C. Reding Home Inspector #38663	On or about September 20, 2007, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>condition of furnace propane tank located in front yard; advise client of the lack of insulation at floor structure in crawl space; report on crawl space ventilation; report method used to observe crawl space and attic components; report type and condition of plumbing waste/vent piping; and recommend a corrective action for lack of laundry room ventilation.</i>	Letter of Reprimand Administrative Penalty – Pay administrative penalty in the amount of \$400.00. Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score. Costs of Investigation – Pay costs of investigation in the amount of \$117.00.
HI08-011	Stephen P. Marchal Home Inspector #39989	On or about March 2, 2006, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>report noisy air conditioning unit; report condition of air filters; type and condition of foundation; floors and walls; condition of front entry steps and safety rails, rear exterior rails; condition of roof drainage systems; plumbing functional flow and functional drainage; water heater safety controls; electrical service ground, lights and switches; report a heat source in each room; and report on presence and condition of laundry ventilation.</i>	Letter of Reprimand Administrative Penalty – Pay administrative penalty in the amount of \$800.00. Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score. Costs of Investigation – Pay costs of investigation in the amount of \$150.00.
HI08-013	Jesse F. Reeves Home Inspector #38989	On or about October 28, 2006, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: include a statement inspection was done in accordance to the Arizona Standards of Professional Practice; failed to obtain a signed inspection agreement before the report was delivered; report presence and condition of HVAC automatic safety controls; plumbing functional flow and drainage; plumbing distribution piping supports and insulation; type and condition of waste piping present; failed to make a recommendation to correct, monitor or evaluate by appropriate persons for double tap found at electrical main panel; operation and condition of electrical switches; over current protection; condition of roof flashings present; and condition of rear patio columns present.	Letter of Reprimand Administrative Penalty – Pay administrative penalty in the amount of \$100.00. Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score. Costs of Investigation – Pay costs of investigation in the amount of \$100.00.
JANUARY 27, 2009			
HI09-001	Willie J. Wade Home Inspector #40517	On or about April 11, 2005, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>report missing attic insulation in the home, and make a recommendation to correct, monitor, or evaluate by appropriate persons.</i>	Letter of Reprimand Restitution - Pay restitution to AJF Engineering in the amount of \$1314.60. Costs of Investigation – Pay costs of investigation in the

			amount of \$100.00.
MARCH 24, 2009			
HI08-014	Paul G. Gonzales Home Inspector #38851	On or about November 1, 2006, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: observation method used to inspect attic; presence and condition of attic ventilation; entry door; garage door opener including safety reversing; plumbing materials present for supply and distribution piping, waste and vent piping; plumbing function flow and functional drainage; type and condition of the electrical service conductor; electrical service ground; branch circuit conductors; operation and condition of the exterior and garage GFCI's devices; presence of a heating and cooling source in each room; and on the presence and condition of bathroom and laundry ventilation.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay administrative penalty in the amount of \$300.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board's Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$105.00.</p>
HI09-015	Ronald R. Luensman Home Inspector #40494	<i>Respondent advertised by email an offer to valley realtors at his firm's website, a \$50.00 gas card or \$50.00 Visa gift card for referral's to Realtors during the month of January 2009. If a client entered into an inspection agreement for a home inspection done by Central Home Inspections.</i>	<p>Assurance of Discontinuance</p> <p>Administrative Penalty – Pay administrative penalty in the amount of \$500.00.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$90.00.</p>
HI09-016	Charles G. Hanvey Home Inspector #42480	On or about October 28, 2006, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: condition of the foundation; wall flashings; trim; water heater; electrical service; service ground; overcurrent protection devices; electrical compatibility; light fixtures; attic and laundry ventilation; piping supports and insulation; type and condition of roof structure; describe observation method used to inspect attic; type of waste type piping present; plumbing function flow and functional drainage; condition of the and presence of a heating and cooling source in each room.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay administrative penalty in the amount of \$200.00.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$100.00.</p>
APRIL 28, 2009			
M06-108	Genny L. Setford Home Inspector #39317	On or about July 18, 2005, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: type and condition of floors, walls condition; under floor crawl space condition and ventilation present, and observation method used; type plumbing waste and vent	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay administrative penalty in the amount of \$250.00.</p> <p>Open Book Test – Take and successfully complete an open</p>

		<p>pipng material present; fuel distribution piping and supports; type and condition of attic insulation; type and condition of plumbing pipe supports and insulation; and failed to make recommendations to correct, monitor, or evaluate by appropriate persons adverse conditions regarding the front and rear steps.</p>	<p>book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$117.00.</p>
HI07-093	David J. Marshall Home Inspector #38146	<p>On or about August 5, 2005, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>condition of the roof</i>; type and condition of electrical branch circuit conductors; heating and cooling system filters; condition of attic ventilation; condition of the ceiling structure; and a representative number of electrical lights and switches.</p>	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$500.00.</p> <p>Probation until the following is met:</p> <p>Restitution - Pay restitution to Ms. Mitchell in the amount of \$300.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$180.00.</p>
HI08-015	Arthur O. Gregory Home Inspector #45992	<p>On or about August 14, 2007, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>failed to meet the minimum reporting requirements 41 areas of concern; failed to give the client a better understanding of the property conditions at the time of the inspection; failed to state many systems and components inspected were in need of immediate major repair; and failed to make recommendation for further evaluation by appropriate persons on adverse conditions present.</i></p>	<p>Letter of Reprimand</p> <p>Voluntary Surrender – Deemed to be a Revocation, Respondent agrees to voluntarily surrender his home inspector registration #45992.</p> <p>Restitution - Pay restitution to Ms. Tokioka in the amount of \$250.00.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$190.00.</p>
HI08-022	Raymond G. Zylla Home Inspector #38072	<p>On or about July 24, 2007, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: type and condition of walls; type and condition of fuel distribution systems; condition of heating system automatic safety controls; condition of plumbing distribution piping; type and condition of plumbing waste and vent piping; failed to make a recommendation to repair a missing heating and cooling source in the family room; and make a recommendation to repair missing dryer ventilation.</p>	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$100.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$155.00.</p>

HI09-017	Daniel E. Haydon Home Inspector #38067	On or about December 4, 2008, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>properly report on 3 central air conditioners present; and lack of a heating source in the main structure.</i>	<p>Letter of Reprimand</p> <p>Restitution - Pay restitution to Ms. Kuehn in the amount of \$400.00.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$78.00.</p>
----------	---	---	---

JUNE 23, 2009

HI07-076	Bradley A. Perkins Home Inspector #40390	On or about April 11, 2006, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>adequately report the condition of the roof; and leaking kitchen stove vent flashing</i> ; type of flat roof covering present; type of heating and cooling energy source present; report on heating and cooling filters; and a heating and cooling source in each room.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay administrative penalty in the amount of \$300.00.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$340.00.</p>
----------	---	--	---

HI09-011	Kevin M. Junior Home Inspector #39645	On or about June 7, 2007, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>correctly identify polybutylene pipes present</i> ; condition of columns; HVAC filters, attic ventilation; exterior wall and roof flashings, eaves and soffits; plumbing copper distribution piping; and heating automatic safety controls.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$100.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$100.00.</p>
----------	--	--	--

HI09-014	Douglas B. Mason Home Inspector #38656	On or about December 17, 2008, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: include inspectors name in the report; type and condition of floors; entryway doors; plumbing functional flow and functional drainage; failed to make a recommendation for aluminum branch circuit wiring present; and report on the presence of an installed cooling and heating source in each room.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$100.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$105.00.</p>
----------	---	---	--

HI09-021	William J. Hoge Home Inspector #39186	On or about July 11, 2008, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: condition of the ceiling structure; type of plumbing distribution, waste, and vent piping present; plumbing function drainage; presence of a heating and cooling source in each room; type and condition of cooling equipment present; reported on several items condition as satisfactory with adverse conditions present; and condition of the crawl space.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$300.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$103.00.</p>
HI09-022	Thomas R. Rider Home Inspector #43778	On or about May 10, 2008, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: obtain a signed agreement; refer to the Arizona Standards of Professional Practice in agreement; condition of the windows; second (metal) roof; method used to observe the roof; plumbing functional flow and functional drainage; water heater and automatic safety controls; electrical system switches; heating and cooling source in each room; attic ventilation; and type and condition of the evaporative cooler present.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$300.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$103.00.</p>

AUGUST 25, 2009

HI10-004	Virendra T. Manaktala Nonregistrant	Respondent is not registered in the State of Arizona to perform home inspections. <i>Respondent admitted to performing home inspections and issuing home inspection reports while having expired registration from November 23, 2007 to August 7, 2009 in violation of A.R.S. § 32-145(1) in that it is unlawful for a Nonregistrant to practice or hold himself out as qualified to practice home inspections without certification. Respondent advertised his company on the web at www.azhomecheck.com stating he was a registrant of the Arizona State Board of Technical Registration. Respondent advertised by handing out business cards stating he was Arizona certified registrant #40001 in violation of A.R.S. § 32-145 (2). Respondent’s firm registration expired on June 30, 2007, Arizona Home Check Professional Home Inspections, L.L.C. offered home inspection services to the public without firm registration in violation of A.R.S. § 32-141 (A)(D). Respondent’s Financial Assurance expired September 12, 2007 in violation of A.R.S. § 32-122.02 (C).</i>	<p>Assurance of Discontinuance</p> <p>Civil Penalty – Pay a civil penalty in the amount of \$12,000.00.</p> <p>Costs of Investigation – Pay cost of investigation in the amount of \$150.00.</p>
----------	--	---	---

REFERRED FOR CRIMINAL PROSECUTION

M04-230 M05-329	James J. Canino Nonregistrant	<i>Respondent is not registered in the State of Arizona to perform home inspections.</i>	Class 3 Felony conviction on October 18, 2008 for Fraudulent Schemes and Artifices.
--------------------	----------------------------------	--	--

M06-263 M06-299 HI07-007 HI07-063 HI07-064		<p><i>On or about March 7, 2004 to July 24, 2006, Respondent performed various home inspections without valid certification, firm registration, or financial assurance. Respondent pled guilty in Superior Court in the State of Arizona on 10/17/2008.</i></p> <p>Offense: Count 1 Attempted Fraudulent Schemes and Artifices Class 3 felony, in violation of A.R.S. §§ 13-2310, 13-2301, 13-701, 13-702, 13-702.01, 13-702.02 and 13-801. Non Dangerous – Non Repetitive offense under the criminal code.</p>	<p>Superior Court ordered criminal sentence – 2 years probation.</p> <p>Other court ordered sanctions – Restitution to home owners.</p>
--	--	--	---

SEPTEMBER 22, 2009

HI10-006	James S. Seldon Nonregistrant	<p><i>While having a pending home inspector application for certification. Respondent offered a contract to conduct a home inspection and issue an inspection report for the fee of \$240.00 without individual registration in violation of A.R.S. § 32-145 (1). This was offered on August 20, 2009 to State Investigators for the Board of Technical Registration posing as members of the public. Respondent advertised professional home inspections to the public on his website www.echoinspectors.com offering for approximately 3 months in violation of A.R.S. § 32-141 (A)(D) and A.R.S. § 32-145 (3). Respondent handed out business cards and brochures offering home inspection services in Arizona for approximately 3 months in violation of A.R.S. § 32-145 (2). Respondent placed magnetic signs advertising home inspection services to the public on his vehicle in violation of A.R.S. § 145 (2). Respondent offered home inspection services to the public without financial assurance on August 20, 2009. Additionally, Respondent advertised his firm Echo Canyon Home Inspectors without firm registration in violation of A.R.S. § 32-141 (A)(D).</i></p>	<p>Letter of Reprimand</p> <p>Assurance of Discontinuance</p> <p>Home Inspector application – Respondent shall pay civil penalty in full before application will be processed.</p> <p>Probation – Respondent shall be placed on probation for 1 year if certification is granted by the Board.</p> <p>Civil Penalty – Pay a civil penalty in the amount of \$2000.00.</p> <p>Costs of Investigation – Pay cost of investigation in the amount of \$98.00.</p>
----------	----------------------------------	---	---

OCTOBER 27, 2009

HI09-018	Mitchell B. Holt Home Inspector #40509	<p><i>On or about February 15, 2008, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: Failed to properly report a missing emergency overflow drain pan for the HVAC air handler; state that the inspection was conducted in accordance with the Standards of Professional Practice for home inspectors in the State of Arizona; include the firm’s address in the inspection agreement; condition of the concrete slab; plumbing pipe supports and functional drainage; type of plumbing waste and vent piping material present; condition of main electrical panel, distribution panels, branch circuit conductors, and service conductors; type and condition of AC distribution system; condition of the insulation; accurately report heating system flues and vents;</i></p>	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$800.00.</p> <p>Probation until the following is met: Restitution - Pay restitution to Mr. & Mrs. Mills in the amount of \$315.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the</p>
----------	---	--	---

		<i>and condition of the wall structure.</i>	amount of \$146.00.
JANUARY 26, 2010			
HI10-011	Richard J. Dinolfi Nonregistrant	Respondent is not registered in the State of Arizona to perform home inspections. <i>Respondent offered home inspection services in Arizona without individual registration in violation of A.R.S. § 32-145 (1). Respondent contracted to conduct a home inspection and issued an inspection report for the fee of \$300.00. This was offered on or about October 14, 2009 to Mr. & Mrs. Wilson, a complaint was received on that inspection. Respondent handed out business cards offering home inspection services in Arizona in violation of A.R.S. § 32-145 (2). Respondent offered home inspection services to the public without financial assurance. Respondent offered home inspection services as Parker Home Inspectors without firm registration in violation of A.R.S. § 32-141 (A)(D).</i>	Assurance of Discontinuance Civil Penalty – Pay a civil penalty in the amount of \$2000.00. Restitution - Pay restitution to Mr. & Mrs. Wilson in the amount of \$300.00. Costs of Investigation – Pay cost of investigation in the amount of \$127.00.
FEBRUARY 23, 2010			
HI10-016	Saad Sean Shoucair Nonregistrant	Respondent is not registered in the State of Arizona to perform home inspections. <i>Respondent offered home inspection services in Arizona while having a revoked certification in violation of A.R.S. § 32-145. Respondent handed out business cards offering home inspection services in Arizona for approximately one year in violation of A.R.S. § 32-145 (2). Respondent advertised a former employees inspector certification number in his advertising materials without that inspectors knowledge in violation of A.R.S. § 32-145 (4). Respondent offered home inspection services to the public without financial assurance. Respondent offered home inspection services as 1st Choice Home Inspections without firm registration in violation of A.R.S. § 32-141 (A)(D).</i>	Assurance of Discontinuance Civil Penalty – Pay a civil penalty in the amount of \$8000.00. Costs of Investigation – Pay cost of investigation in the amount of \$162.00.
APRIL 27, 2010			
HI10-002	Robert J. Jeglum Home Inspector #42690	On or about March 20, 2009, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>Failed to report dry rotted wood at the porch and unstable porch railings, water damaged wood in the attached shed;</i> type of wall cladding; type and condition of columns; condition of the roof/ceiling structure; under floor crawl space, ventilation and the method used to observe, plumbing supply piping supports & insulation, vapor retarder in crawl space, floor structure; porch railings; plumbing supply and distribution piping materials; attic ventilation; Failed to make a recommendation	Letter of Reprimand Administrative Penalty – Pay an administrative penalty in the amount of \$1000.00. Probation until the following is met: Restitution - Pay restitution to Mr. & Mrs. Lindbo in the amount of \$255.00. Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days

		regarding inability to locate electrical system service ground; and condition of the HVAC filter.	until passing with a 100% score. Costs of Investigation – Pay costs of investigation in the amount of \$226.00.
HI10-009	Guy D. Minarsich Home Inspector #42076	On or about June 17, 2009, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>Failed to report kitchen sink piping exiting the back wall and draining into backyard</i> ; Failed to include Inspectors name, certification number, and firm address in agreement; condition of water heater combustion air ventilation / safety controls; furnace combustion air ventilation; laundry dryer venting; wall structure; main roof covering; electrical service ground; and branch-circuit conductors.	Letter of Reprimand Administrative Penalty – Pay an administrative penalty in the amount of \$1000.00. Probation until the following is met: Restitution - Pay restitution to Mr. Coyle in the amount of \$285.00. Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score. Costs of Investigation – Pay costs of investigation in the amount of \$187.00.
HI10-018	Lord John Robert Berendt III Nonregistrant	Respondent is not registered in the State of Arizona to perform home inspections. <i>Respondent handed out brochures offering several services including home inspections without certification by the Board of Technical Registration in violation of A.R.S. § 32-145(2). On or about December 2009 thru January 13, 2010 Respondent offered home inspection services on his website in violation of A.R.S. § 32-145(1). A Craigslist add listed January 1, 2010 gave his web address offering home inspection services in Arizona. During the time advertisements were offered no inspections were conducted by Respondent, if a home inspection was booked the intent was to allow a licensed home inspector to be booked to perform the actual service.</i>	Assurance of Discontinuance Civil Penalty – Pay a civil penalty in the amount of \$500.00. Costs of Investigation – Pay costs of investigation in the amount of \$90.00.

HI10-020	Patrick Holmes Nonregistrant	<p><i>Respondent conducted home inspection services in Arizona while having a lapsed certification in violation of A.R.S. § 32-145 (1). Respondent handed out business cards offering home inspection services in Arizona in violation of A.R.S. § 32-145 (2). Respondent advertised his certification number on his business cards advertising state certified inspector in violation of A.R.S. § 32-145 (3)(4). Respondent offered home inspection services to the public without financial assurance in violation of A.R.S. § 32-122.02. Respondent advertised on his vehicle with magnetic signs reading Holmes Property Inspection in violation of A.R.S. § 32-145(2). Additionally, Respondent offered home inspection services as Holmes Home Inspection without firm registration in violation of A.R.S. § 32-141 (A)(D).</i></p>	<p>Assurance of Discontinuance</p> <p>Civil Penalty – Pay an administrative penalty in the amount of \$10,000.00.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$250.00.</p>
AUGUST 24, 2010			
HI09-020	Ronald C. Fillet Home Inspector #38567	<p>On or about October 3, 2008, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>Failed to report the inoperative garage light and outlet defects; Failed to report on the tub/shower cracks, plumbing pipe supports, and defective drain stopper; multiple plumbing valve fixtures corroded and damaged; and report a broken window covered with wood.</i> Failed to include a reference to the Arizona Standards of Professional Practice; foundation; floor and wall structures; columns; plumbing supply piping supports; electrical service conductor material; main electric panel; report the presence of a heating and cooling source in the kitchen; vapor retarder; receptacles in the garage; electrical service voltage present; failed to include the address of the inspector in the inspection agreement; and Used the word "COMMENT" in the report as an acceptable condition then listed adverse conditions found on the same items.</p>	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$1500.00.</p> <p>Probation until the following is met:</p> <p>Restitution - Pay restitution to Ms. Fallis in the amount of \$240.00.</p> <p>Professional Peer Review - Submit for peer review the next three (3) home inspection reports done within 90 days of the effective date of the Consent Agreement.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$165.00.</p>
HI10-003	Thomas L. Culpepper Home Inspector #39422	<p>On or about April 19, 2005, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>Failed to report the type of interior supply piping as polybutylene piping.</i> Failed to obtain a signed inspection agreement prior to delivering inspection report;</p>	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$1500.00.</p> <p>Probation until the following is met:</p>

		roof/ceiling structure; garage door opener; plumbing functional flow; electric system lights, GFCI protection; report on the presence of a heating/cooling source in each room; interior railings; kitchen, laundry, and bathroom ventilation; plumbing fixtures and faucets; bathroom outlets & switches; counters & cabinets in kitchen and bathrooms; and heating & cooling distribution systems.	<p>Restitution - Pay restitution to Ms. Taylor in the amount of \$250.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$165.00.</p>
HI10-008	Larry M. Abell Home Inspector #40408	On or about March 24, 2005, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>Failed to report the type of interior supply piping as polybutylene piping</i> ; roof and ceiling structures; skylight; waste and vent piping; functional drainage; fuel piping; GFCI Protection in bathrooms; HVAC distribution system; HVAC air filters; HVAC source in each room; attic insulation; stairs, steps, balconies, rails, and intermediate floor structure in two story home; laundry dryer vent, and attic ventilation.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty in the amount of \$1500.00.</p> <p>Probation until the following is met:</p> <p>Restitution - Pay restitution to Mr. & Mrs. Self in the amount of \$275.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$131.00.</p>
DECEMBER 21, 2010			
HI10-021	Joseph D. Aloisio Home Inspector #49811	On or about December 19, 2009, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>Failed to report the condition of the evaporative cooler</i> ; type of foundation; condition of the HVAC system automatic safety controls; type of columns; condition of the fuel distribution system pipe supports; plumbing system functional drainage; and a statement that the inspection is performed in accordance with the Standards of Professional Practice for Arizona Home Inspectors.	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay administrative penalty in the amount of \$1000.00.</p> <p>Probation until the following is met:</p> <p>Restitution - Pay restitution to Ms. McKinney in the amount of \$255.00.</p> <p>Open Book Test – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p>Costs of Investigation – Pay costs of investigation in the amount of \$143.00.</p>
HI10-022	Norier Shirvanian Home Inspector #38976	On or about January 7, 2009, Respondent performed a home inspection and prepared a report that failed to meet the Standards of Professional Practice for Arizona Home Inspectors by failing to adequately address the following areas: <i>Failed to report the</i>	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay administrative penalty in the amount of \$500.00.</p>

		<p><i>condition of the patio roof; plumbing functional flow and functional drainage; type plumbing waste & vent pipe material; and heating system automatic safety controls.</i></p>	<p><i>Probation until the following is met:</i> <i>Restitution</i> - Pay restitution to Mr. & Mrs. Phillips in the amount of \$370.00.</p> <p><i>Open Book Test</i> – Take and successfully complete an open book test on the Board’s Statutes and Rules within 30 days until passing with a 100% score.</p> <p><i>Costs of Investigation</i> – Pay costs of investigation in the amount of \$147.00.</p>
--	--	--	--